



(4) #10x3" screws (8) #10x1/2" screws




How To Screen A PCA Door




- 1. Roll Top Spline
- 2. Pull Screen Snug and Roll Bottom Spline
- 3. Roll Left Spline
- 4. Roll Right Spline


If your door does not have a push bar, skip to Step 9.

5. Cut Screen at Both Ends of Push Bar (see Step 5 illustration)



- 6. Split Screen At Push Bar (See Step 6 illustration)
- 7. Roll Top of Push Bar
- 8. Roll Bottom of Push Bar
- 9. Trim Tabs (See Step 9a and 9b illustrations)






Roller

Flat Spline

Frame

How To Roll Spline

Screen



Step 6